DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: <a href="mailto:lsb@dhw.idaho.gov">lsb@dhw.idaho.gov</a>

March 9, 2010

Richard Davis, Administrator Boise Group Home #8-- Delmar 2 PO Box 4243 Boise Idaho 83711

RE: Boise Group Home #8-- Delmar 2, Provider ID# 13G069

Dear Mr. Davis:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Boise Group Home #8 Delmar 2, on March 2, 2010.

Enclosed is your copy of a Statement of Deficiencies/Plan of Correction, form CMS-2567, which states that no Medicaid deficiencies were noted at the time of the survey. Also, enclosed is a similar form stating that no State licensure deficiencies were noted at the time of the survey.

Thank you for the courtesies extended to us during our visit. If we can be of any help to you, please call our office at (208)334-6626.

Sincerely,

TOM MROZ

Health Facility Surveyor

Facility Fire Safety and Construction Program

TM/lj

Enclosure

## DEPARTMENT OF HEALTH AND HUMAN SERVICES

Printed: 03/03/2010 FORM APPROVED

CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING B. WING 13G069 03/02/2010 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER BOISE GROUP HOME #8 (DELMAR #2) 12495 W. DELMAR STREET **BOISE, ID 83713** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLÉTION PRÉFIX (EACH DEFICIENCY MUST BE PRECEEDED BY FULL **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) K 000 INITIAL COMMENTS K 000 The facility is a single story, Type V(000) construction, residential type building. It is fully sprinklered except in attic and garage by a 13 D system with Quick Response heads. There is a complete fire alarm/smoke detection system. It was built in January 1999 and is currently licensed for 5 ICF/MR beds. The facility was found to be in substantial compliance with applicable fire/life safety requirements during the annual Fire/Life Safety survey conducted on March 1st and 2nd 2010. The facility was surveyed under the LIFE SAFETY CODE, 2000 Edition, Chapter 33, Existing Residential Board & Care Occupancies. Impractical Evacuation Capability in accordance with 42 CFR 483,470 (i). The Survey was conducted by: Tom Mroz CFI-II Health Facility Surveyor Fire/Life Safety and Construction

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

PRINTED: 03/03/2010 FORM APPROVED

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING

(X3) DATE SURVEY COMPLETED

13G069

B. WING \_

03/02/2010

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

			2495 W. DELMAR STREET DISE, ID 83713		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY REGULATORY OR LSC IDENTIFYING INFORM	IENCY MUST BE PRECEDED BY FULL		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M 000	16.03.11 Inital Comments		M 000		
	sprinklered except in attic and garage by system with Quick Response heads. T	struction, residential type building. It is fully alklered except in attic and garage by a 13 D arm with Quick Response heads. There is a plete fire alarm/smoke detection system. It built in January 1999 and is currently			
	The facility was found to be in substantial compliance with applicable fire/life safety requirements during the annual Fire/Life Safety survey conducted on March 1st and 2nd 2010. The facility was surveyed under the LIFE SAFETY CODE, 1976 Edition, "Lodging and Rooming Houses " contained in Chapter 11, "Lodging and Rooming House Occupancies " and applicable provisions of Chapters 01 through 07, Chapter 17 and Appendices A and B of the Life Safety Code, Impractical Evacuation Capability in accordance with IDAPA 16.03.11.				
	Tom Mroz Health Facility Surveyor Fire/Life Safety and Construction				
ABORATOR	Y DIRECTOR'S OR PROVIDER/SUPPLIER REPRESE	NTATIVE'S SIG	NATURE	TITLE	(X6) DATE

TITLE

(X6) DATE